





【書類名】 図面

【図1】 FIG. 1



$h_4 = -1.0$




$h_4 = +0.67$



$h_4 = +2.0$



【図2】 Fig. 2



【図3】

Fig. 3 A






Fig. 3 B



【図4】

Fig. 4



S1: Preparation for Measurement

S2: Measurement of Curvature of Field

S3: Setting of Initial Parameter in Design Software

S4: Accurate Determination of  $g$  Value

S5: Setting of Object Height and Meridional Focal Point Position

S6: Definition of Optimizing Function

S7: Optimizing Calculation

[図 5]

Fig. 5




図2




Fig. 6

図3

